

US EPA ARCHIVE DOCUMENT

LANDFILL SITE ASSESSMENT

Facility Name :	Chastang Landfill	Facility Location ID :	110034132686
Assessment Date :	9/4/2010	Incident Name :	BP Spill
Physical Location :	17045 Highway 43		
City, State :	Mount Vernon , AL	County :	Mobile

ASSESSMENT INFORMATION

General Site Information and Observations	
1. Is the facility currently receiving debris from BP?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. If no, has the facility received debris from BP in the past?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Which companies are transporting the BP waste?	Waste Management
4. How many BP waste loads have been rejected?	None
5. If so, why?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Additional Comments : During this operational period John E. Johnston departed for the Chastang Landfill, Mt. Vernon, Mobile County, Alabama at 0630 hours CDT for an assessment of the waste accepted at the facility. The Waste Monitoring Group Supervisor arrived at the landfill at 0715 CDT. An ADEM representative was not present. Matt East, Operations Manager, was present during the Waste Monitoring Group assessment at the Chastang Landfill. Chastang is still receiving BP-generated waste but only approximately 1/3 of the loads are manifested as Oily Contaminated Material.	